

# Work Order ID 55559

January 21, 2010 11:45:40 AM



Page 1

Item ID: D2620

Accept



Setup Start



Revision ID:

Stop



Item Name: Skidtube, 206 Skidtube

Start Date: 1/21/10 Start Qty: 10.00



Cust Item ID:

Required Date: 2/24/10 Req'd Qty: 10.00



Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/  
Work Center ID

Operation  
Description

Set Up/  
Run Hours

Draw  
Number

Draw  
Rev.

Plan  
Code

Accept  
Qty

Reject  
Qty

Reject  
Number

Insp.  
Stamp

Draw Nbr

Revision Nbr

D2620

Rev B

100

0.00



Skidtubes

Skidtubes

Memo

0.00

Skidtubes

1-Bend extrusion as per Dwg D2620 using CNC Bending Machine program  
206.A and Folio Ft008: 2- Cut Fwd end of tube as per Dwg D2620

(10x) Q NB 10-01-21

110

QC5- Inspect part completeness to step on W/O

0.00



QC

Memo

0.00

Quality Control

DP

10-1-21

120

Identify as per dwg & Stock Location: 46

0.00



Packaging

Memo

0.00

Packaging

DP

10-1-21

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

# Work Order ID 55559

January 21, 2010 11:45:40 AM



Page 2

Item ID: D2620

Accept



Setup Start



Revision ID:

Stop



Item Name: Skidtube, 206 Skidtube

Start Date: 1/21/10 Start Qty: 10.00



Cust Item ID:

Required Date: 2/24/10 Req'd Qty: 10.00



Customer:

Reference:

Run Start



Approvals:

Process Plan:

Date:

Tooling:

Date:

Stop



QC:

Date:

SPC (Y/N):

Date:

Sequence ID/  
Work Center ID

Operation  
Description

Set Up/  
Run Hours

Draw  
Number

Draw  
Rev.

Plan  
Code

Accept  
Qty

Reject  
Qty

Reject  
Number

Insp.  
Stamp

130

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

10/01/22

ME 10-1-21

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


**NOTE:** Date & initial all entries

# Picklist Print

January 21, 2010 11:45:39 AM

Page 1  
T

Work Order ID: 55559



Parent Item: D2620

Parent Item Name: Skidtube, 206 Skidtube

Start Date: 1/21/10

Required Date: 2/24/10

Comments: IPP D 02.07.26 Change Dwg to rev.B; Updated Location: RF

Start Qty: 10.00

Required Qty: 10.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2600-1-160		Manufactured	No			100	Each	57.0000	10.0000			



Extrusion Round 3" 206



Warehouse

Loc Qty

Loc Code

Location

Main Warehouse

ST

43969

57

57

10

DP

10-1-21

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_


Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

# SPECIFICATION CONTROL DRAWING

## 206 SKIDTUBE BENDING



### DAMAGE TOLERANCE

1. THERE SHOULD BE NO VISIBLE WRINKLES BELOW 5.0 AFTER BENDING.
2. GOUGES UP TO 0.020 DEEP ARE ACCEPTABLE IN BENT PORTION OF THE TUBE. NO GOUGES ARE ACCEPTABLE IN THE FLAT PORTION OF THE TUBE. DEEPER GOUGES ARE ACCEPTABLE IN THE PORTION OF THE TUBE ABOVE 5.0.
3. TUBE WIDTH SHOULD BE  $3.20 \pm 0.200$  IN THE BEND. TUBE WIDTH SHOULD BE  $3.200 \pm 0.010$  IN THE FLAT PORTION OF THE TUBE.
4. TUBE HEIGHT SHOULD BE  $3.15 \pm 0.200$  IN THE BEND. TUBE HEIGHT SHOULD BE  $3.150 \pm 0.010$  IN THE FLAT PORTION OF THE TUBE.

NOTE: ALL DIMENSIONS ARE IN INCHES

DART



DESIGN	DRAWN BY	DART AEROSPACE USA, INC.
CHECKED	APPROVED	FAIRCHILD INTERNATIONAL AIRPORT, WA
DATE	TITLE	REV. B
99.09.10	206 SKIDTUBE BENDING CONTROL	SHEET 1 OF 1
A	NEW ISSUE	SCALE
B	UPDATE FOR IN-HOUSE BENDING	

RELEASED

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries